

Phillips Point Size Chart

Point Size	WOOD SCREW SIZE		MACHINE SCREW SIZE				SHEET METAL SCREW SIZE			
	Flat Oval	Round	Binding Flat	Binding Oval	Round Fillister	Truss Brazier	Truss Button	Binding Oval	Flat Round	Flat Stove
0	0-1	0-1	0-1		0-1		0-1			0-1
1	2-3-4	2-3-4	2-3-4		2-3-4		2-3-4-5			2-3-4
2	5-6-7-8-9	5-6-7-8-9-10	5-6-8-10		5-6-8-10		6-8-10			5-6-7-8-10
3	10-12-14-16	12-14-16	12-1/4		12-1/4-5/16		12-1/4			12-14
4	18-20-24	18-20-24	5/16-3/8-7/16-1/2		3/8-7/16-1/2		5/16-3/8-7/16-1/2			-

1/4" Hex Insert



Part #	Point Size	Overall Length		Features
		In	mm	
PO	0	1	25.4	
P1	1	1	25.4	
P2	2	1	25.4	
P3	3	1	25.4	
P4	4	1	25.4	
P1-FX	1	1	25.4	Full Hex
P2-FX	2	1	25.4	Full Hex
PR1	1	1	25.4	Reduced Diameter
PR2	2	1	25.4	Reduced Diameter
P2-15	2	1 1/2	38.1	
P1-20	1	2	50.8	
P2-20	2	2	50.8	
P3-20	3	2	50.8	

1/4" Hex Power Drive



Part #	Point Size	Overall Length		Features
		In	mm	
PO-2	0	1 15/16	49.2	
P1-2	1	1 15/16	49.2	
P2-2	2	1 15/16	49.2	
P3-2	3	1 15/16	49.2	
P1-3	1	2 3/4	69.9	
P2-3	2	2 3/4	69.9	
P3-3	3	2 3/4	69.9	
P1-4	1	3 1/2	88.9	
P2-4	2	3 1/2	88.9	
P3-4	3	3 1/2	88.9	
P1-6	1	6	152.4	
P2-6	2	6	152.4	
P3-6	3	6	152.4	